SYSLOG Error: "WARNING: <brickid> ATTN: TEMP 5 advisory temperature reached @ 30 C/ 86 F."

Published 08/20/2001

Symptom(s):

```
ESP Class Description: System Controller
SYSLOG Error: "WARNING:

     ATTN: TEMP 5 advisory temperature reached @ 30 C/ 86 F."

ESP Event Type Id: 351
ESP Type Description: Temperature advisory limit reached
```

Fact(s):

```
SGI Origin 3000
IRIX 6.5.X
SGI Onyx 3000
```

SGI Solution:

```
This error will occur when the temperature of the system is too high.  Possible causes for this are:
1) The first thing to check is if the room temperature is too high.
2) Next check if a fan has failed in the brick, which means the temperature isn't being regulated properly.

Note: This solution was automatically retrieved by Embedded Support Partner (ESP).  For questions regarding this solution or for any
additional troubleshooting assistance please contact your support provider.
```

Cause(s):

```
The room temperature is too high or cooling fans are failing.
```

Answers others found helpful

- How to set brick rack and unit position

Additional Details

Creation Date	06/01/2001 06:11 AM
Last modification	01/15/2016 04:29 PM
Published Date	08/20/2001
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution